DRAFTING - TEXT HEIGHTS

Upper-case letters should normally be used. Use lower-case letters for conventional signs and symbols that normally require such characters (such as: mm, kg, kPa).

Text Applications	Text Height (mm)				
	A4	A3	A2	A1	Ao
Reference information, such as File Name and Notes within the Drawing Frame.		1.8		2.	5
Data Text within Data Tables (including BOM, Revision Table). Dimensions and Leaders. Dimensioning Symbols. Notes. Reference Symbols.		2.5		3	•5
Auxiliary View Symbols. Headings within Data Tables (optional). Section Line Symbols. Sub-Titles. View Labels or Sub-Titles.		3.5		5.	.0
Drawing Numbers. Titles.		5.0		7.	0
		7.0		10	.0